INSPECTION REPORT

Name of work	Ward Maintanance for Gangmens & Tractor for 2nd Shift 6.00 A.M to 2.00 P.M Removing silt & debries in the drains road side burms in Dasarahalli ward No 15
BR No	507/28-10-2016 507/28-10-2016.
Agency	JAYAMMA K
Worl Order No	BBMP/DZ/EE/DD/WO/260/13-14 Dated:29-5-2014 (Modified)
Est Amt	12.00 000.00
Bil Amt	1196855.00
Job Code	015-14-000024
P Code	1771
Date of Inspection	

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಧಿಯಂತರು
ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned by CamScanner



Scanned by CamScanner

INSPECTION REPORT

Name of work	Ward Maintanance for Gangmens & Tractor for 2nd Shift 6.00 A.M to 2.00 P.M Removing silt & debries in the drains road side burms in Dasarahalli ward No 15
BR No	507/28-10-2016 507/28-10-2016
Agency	JAYAMMA K
Worl Order No	BBMP/DZ/EE/DD/WO/260/13-14 Dated:29-5-2014 (Modified)
Est Amt	12.00 000.00
Bil Amt	1196855.00
Job Code	015-14-000024
P Code	1771
Date of Inspection	

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರು
ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned by CamScanner